

SPECPARTS LIST

No.	Description	Qty	No.	Description	Qty	No.	Description	Qty
1	Upper crossbeam	1	20	Washer $\Phi 12$	12	39	Bolt M12X25	2
2	Cylinder	1	21	Nut M12	12	40	Pump base	1
3	Bolt M30X100	8	22	Post support	4	41	Bolt M12X25	4
4	Washer $\Phi 30$	8	23	Bolt M12X25	12	42	Clip	1
5	Spring washer $\Phi 30$	8	24	Post base left	1	43	Bolt M6X30	1
6	Nut M30	8	25	Bolt M12X40	8	44	Spring washer $\Phi 6$	3
7	Left post	1	26	Washer $\Phi 12$	8	45	Bolt M6X12	2
8	Pin	4	27	Nut M12	8	46	Hose	2
9	Wheel	2	28	Bottom crossbeam	2	47	Pump	1
10	R-pin	4	29	Switch	1	48	Working table	1
11	Bolt M10X30	3	30	Wheel	2	49	Clip	4
12	Winch	1	31	Handle	1	50	Arbor plate	2
13	Washer $\Phi 10$	3	32	Right post	1	51	Spring	4
14	Nut M10	3	33	Post base right	1	52	Bolt	3
15	Winch base	1	34	Spring washer $\Phi 12$	4	53	Nut M12	3
16	Bolt M10X30	4	35	Nut M12	4	54	Square shaft	2
17	Washer $\Phi 10$	4	36	Support	2	55	Wheel	4
18	Nut M10	4	37	Spring washer $\Phi 12$	2	56	Ring 20	4
19	Pin	2	38	Nut M12	2	57	Bolt	1
A1	handle	1	A6	mesh	1	A11	wheel	4
A2	bolt M6X20	2	A7	bush	4	A12	shaft sleeve	4
A3	washer $\Phi 10$	2	A8	bolt M10x50	4	A13	bolt M10X35	4
A4	nutM6	2	A9	Hand wheel	2			
A5	frame	1	A10	mounting plate	2			
B1	0.5" Ram	1	B5	2" Ram	1	B9	Plate	1
B2	0.75" Ram	1	B6	Ram connector	1	B10	Bolt M10X25	2
B3	1" Ram	1	B7	Bolt M8x20	1	B11	Washer $\Phi 10$	2
B4	1.5" Ram	1	B8	Ram base	1	B12	Nut M10	2

DISASSEMBLE DRAWING

